



MATERIAL SAFETY DATA SHEET

For FLUTTERFREE™ Sound Diffusing Wood Products

1. PRODUCT IDENTIFICATION

TRADE NAMES: (AS LABELED)	FLUTTERFREE® FLUTTERFREE® T FLUTTERFREE® W
MANUFACTURER'S NAME:	RPG ACOUSTICAL SYSTEMS, LLC.
ADDRESS:	99 SOUTH ST. PASSAIC, NJ 07055
PHONE NUMBER:	(973)-916-1166
DATE PREPARED OR REVISED:	APRIL 18, 2022

2. COMPONENTS

CHEMICAL NAMES	CAS #	PERCENT	AGENCY	EXPOSURE LIMITS	COMMENTS
Solid Wood Lumber	-	100%	OSHA	PEL-TWA 15.0 mg/m ³	Total dust (PNOR)
			OSHA	PEL-TWA 5.0 mg/m ³	Respirable dust fraction (PNOR)
			ACGIH	TVL-TWA 1mg/m ³	Inhalable fraction
	-				

3. HAZARD IDENTIFICATION

Overview: Manual or mechanical cutting processes performed on the panel can result in generation of wood dust.

Primary Health Hazards: Wood dust.

Warning: Wood dust may present a combustion hazard if a sufficient concentration is suspended in proximity to an ignition source. Users of wood products are advised to assess combustibility hazards.

Primary Route(s) of Exposure:

Skin: Various species of wood fibers may evoke allergic contact dermatitis in sensitized individuals.



Inhalation: Wood fibers may cause nasal dryness, irritation and obstruction. Coughing, wheezing, sneezing, sinusitis and prolonged colds have also been reported.

Eye: Wood fibers can cause mechanical irritation.

Ingestion: Not likely to occur.

Medical Conditions Generally Aggravated by Exposure: Wood fibers may aggravate pre-existing respiratory conditions or allergies.

Carcinogenicity Listing: Wood dust is a known Human Carcinogen, according to the NTP and IARC.

First Aid Procedure:

Eye Contact: Treat dust as foreign object. Flush with water. Seek medical help if irritation continues.

Skin Contact: Seek medical help if dermatitis or irritation persists.

Inhalation: Remove to fresh air. Seek medical help if persistent irritation or coughing, allergic-type responses or difficulty breathing occur.